Tabs

- Inspection
- Results
- Attributes
- Consumables
- Quality Tools

Inspection

Critical Fields

1) Name- Enter the Name of the document.

2) Tester- Name of the person who is inspecting the component.

Critical & onetime setup fields

1) Organization Field- This Field is used to select the organization which you are going to process the order.

2)Target Document Type- This Field is used to select the type of the document that you are going to process.

Non-Critical Fields

1) Total Quantity- System will display the quantity from the selected Material receipt document.User can't edit the Quantity.

2) Sample Quantity- System will display the quantity from the selected Material receipt document.User can't edit the Quantity.

Serial number/Lot number (ASI)

Attribute cant be created in this document.Only attribute will be taken from the selected Source document.

Zoom condition's

1) Material Receipt

2) Shipment (Customer)

3) Subcontract Receipt

4) Inventory Move

5) Internal Use Inventory

6) NCR

Customization

Results

Critical Fields

1) Parameter- Multiple parameters may be there for inspecting a product.This will be shown from Test Plan which the user selected for the product.

2) Record Value- The value that acquired in real during Inspecting the parameter need to be entered.

3) Total Qty- Number of quantity which are inspected.

4) Qc outcome (User)- If decision from the system need to changed this option can be used.For using this option need to configure in the test plan against the parameter

Critical & onetime setup fields

Non-Critical Fields

1. Sample Quantity: Sample quantity to be inspected.

2. Reason: Reason for QC Outcome (User), being entered by user manually.

Serial number/Lot number (ASI)

Zoom condition's

Validation

Attributes

Critical Fields

Field name with Definition

Critical & onetime setup fields

Non-Critical Fields

Serial number/Lot number (ASI)

If there multiple attribute for single product this will display in attributes Sub tab.

Zoom condition's

Validation

Consumables

Critical Fields

1) Product- Enter or select the product that needs to be consumed.

2) UOM: Unit of Measurement of product to be inspected.

3) Quantity- This field represents the quantity needs to be consumed additionally while inspecting.

4) Charge- For posting cost of the consumed product.

Critical & onetime setup fields

Non-Critical Fields

Serial number/Lot number (ASI)

Zoom condition's

Validation

Quality Tools

It's use to add asset and change test plan.