Tabs

- Inspection
- Results
- Consumables
- Quality Tools

Inspection

Critical Fields

1) Name- Enter the Name of the document.

2) Tester- Name of the person who is inspecting the component.

Critical & onetime setup fields

1) Organization Field- This Field is used to select the organization which you are going to process the order.

2)Target Document Type- This Field is used to select the type of the document that you are going to process.

Non-Critical Fields

1. Description: To note Specifics required with documents and to describe other important information.

2. Reason: Reason for QC Outcome (User), being entered by user manually.

Serial number/Lot number (ASI)

Serial number can be selected from previous document.User cant create new serial number in this document.

Zoom condition's

1) NCR

Customization

Results

Critical Fields

1) Parameter- Multiple parameters may be there for inspecting a product.This will be shown from Test Plan which the user selected for the product.

2) Record Value- The value that acquired in real during Inspecting the parameter need to be entered.

3) Total Qty- Number of quantity which are inspected.

4) Qc outcome (User)- If decision from the system need to changed this option can be used.For using this option need to configure in the test plan against the parameter.

Critical & onetime setup fields

Non-Critical Fields

Serial number/Lot number (ASI)

Zoom condition's

Validation

Consumables

Critical Fields

1) Product- Enter or select the product that needs to be consumed.

2) UOM: Unit of Measurement of product is to be inspected.

3) Quantity- This field represents the quantity needs to be consumed additionally while inspecting.

4) Charge- For posting cost of the consumed product.

Critical & onetime setup fields

Non-Critical Fields

Serial number/Lot number (ASI)

Zoom condition's

Validation

Quality Tools

It's use to add asset and change test plan.