

Quality

The screenshot shows the KONECT ANALYTICS web application interface. The top navigation bar includes the logo, a search bar with 'product' entered, and user information: 'Prasanth P@Kconnect Demo.*Kconnect Demo Admin' with links for Feedback, Profile, Preference, Change Role, and Log Out. The left sidebar has 'Favourites' and 'Recent Items' sections. The main content area is titled 'Product: 1000000 Copper Pipes' and shows a 'Data requested' section with the following fields:

- Client:** Kconnect Demo
- Product:** 1000000_Copper Pipes
- Quality plan:** Visual Inspection

Below these fields are two columns of checkboxes for quality checks:

Field	Value
<input type="checkbox"/> IsQCAny	
<input checked="" type="checkbox"/> IsQcMaterialReceipt	
<input type="checkbox"/> IsQcMaterialReceiptprd	
<input type="checkbox"/> IsQcMaterialMove	
<input type="checkbox"/> RMA(Customer)	
<input checked="" type="checkbox"/> Active	
<input checked="" type="checkbox"/> IsQcMaterialIssue	
<input type="checkbox"/> IsQcMaterialIssueprd	
<input type="checkbox"/> IsQcPhysical	
<input type="checkbox"/> Shipment(Customer)	
<input checked="" type="checkbox"/> IsQcSubContract	

Critical Fields

Critical & onetime setup fields

1. Quality Plan : We can give the Quality Plan for the quality checking .
2. Organization Field- This Field is used to select the organization which you are going to process the document.

Non-Critical Fields

1. IsQCAny : This check box is used to check the quality for below all places.
2. IsQcMaterialReceipt : This check box is used to check the quality check in the material receipt window.(Before complete)
3. IsQcMaterialReceiptprd : This check box is used to check the Production Receipt.(Store Receipt)
4. IsQcMaterialMove : This check box is used to check the Inventory Move.
5. RMA(Customer) : This check box is used to check the Customer Return.
6. isQcMaterialIssue : This check box is used to check the material issue places.(Store issue)
7. isQcMaterialIssueprd : This check box is used to check the Material issue production.
8. isQcPhysical : This check box is used to check the physical quantity transaction places.(Physical inventory)
9. Shipment(Customer) : This check box is used to check the Shipment (Customer) window.

10. isQcSubContract : This check box is used to check the subcontract receipt window.(Before Complete)

Zoom condition's

Validation

Revision #7

Created Mon, Apr 13, 2020 8:38 PM by [Prasanth P](#)

Updated Wed, Aug 9, 2023 3:19 PM by [Mukund Tulshiram](#)