

Introduction

- Introduction

Introduction

Introduction

This report display the quality control plan which includes multiple parameters for inspecting a component.

Business Example

In a manufacturing Industry Quality Person will prepare a quality plan for inspecting a product. The quality plan consist of multiple parameters with its predefined range value for inspecting. This report is helpful to view the complete test plan for a product.