

Consumables

KONECT ANALYTICS

Home (19391) Summary *Quality Inspection(Single)... x

Feedback Profile Preference Change Role Log Out

Inspection > Consumables

Inserted

Client: XYZ Foundation

Organization: HQ

Inspection: 1000726_test

Phys Inventory Line

Description

Quality Consumables

Product

UOM

Quantity: 0

Charge

Activate Windows
Go to Settings to activate Windows.

Critical Fields

- 1) Product- Enter or select the product that needs to be consumed.
- 2) UOM: Unit of Measurement of product to be inspected.
- 3) Quantity- This field represents the quantity needs to be consumed additionally while inspecting.
- 4) Charge- For posting cost of the consumed product.

Critical & onetime setup fields

Non-Critical Fields

Serial number/Lot number (ASI)

Zoom condition's

Validation

Revision #4

Created Thu, Apr 16, 2020 4:45 AM

Updated Fri, Aug 11, 2023 1:20 PM by [Mukund Tulshiram](#)