

Inspection

Image not found or type unknown

Home (99) Quality Inspection(Single)... x

Inspection [1/186]

Inventory Move

Quality plan Ball Bearing

QC Outcome(System) QC Not OK

QC Outcome(User) QC OK

Manufacturing Cost Collector

Subcontract receipt

Production

Total Qty 10.00

Sample Qty 10.00

Tester Vijayakumar.S

Reason

Reference Document

Allow Multi Trials

Customer RMA

Phys.Inventory

Manufacturing Order

Create lines from

Status

Document Status Completed

Approved Level 1

Approved Level 2

Approved

Processed

DocumentAction

Results Quality Tools Attributes Consumables Quality Tools

1 Records

Organization	PlanAsset	Asset Group	Asset	Description	Active
Manufacturing Discrete	1000286	1000057_TOOLS	A1000000_DHG - 02-DI...		<input checked="" type="checkbox"/>

Critical Fields

- 1) Name- Enter the Name of the document.
- 2) Tester- Name of the person who is inspecting the component.

Critical & onetime setup fields

- 1) Organization Field- This Field is used to select the organization which you are going to process the order.
- 2) Target Document Type- This Field is used to select the type of the document that you are going to process.

Non-Critical Fields

1) Total Quantity- System will display the quantity from the selected Material receipt document.User can edit the Quantity.

2) Sample Quantity- System will display the quantity from the selected Material receipt document.User can edit the Quantity.

Serial number/Lot number (ASI)

Attribute cant be created in this document.Only attribute will be taken from the selected Source document.

Zoom condition's

1) Material Receipt

2) Shipment (Customer)

3) Subcontract Receipt

4) Inventory Move

5) Internal Use Inventory

6) NCR

Customization

Revision #10

Created Thu, Apr 16, 2020 4:38 AM

Updated Mon, Sep 9, 2024 12:36 PM by [Vijayakumar S](#)