

# Introduction

## Introduction

This report display the quality control plan which includes multiple parameters for inspecting a component.

---

## Business Example

In a manufacturing Industry Quality Person will prepare a quality plan for inspecting a product. The quality plan consist of multiple parameters with its predefined range value for inspecting. This report is helpful to view the complete test plan for a product.

---

Revision #3

Created Sun, May 3, 2020 6:28 PM

Updated Fri, Aug 11, 2023 1:06 PM by [Mukund Tulshiram](#)