

# Tab

- Quality Parameter

# Quality Parameter

The screenshot shows the 'Quality Parameters' setup interface in Konnect Analytics. The form is titled 'Quality parameter' and includes a 'Data requested' section. The fields are as follows:

- Client:** Konnect Demo
- Organization:** Manufacturing Discrete
- Search Key:** Length
- Name:** Length
- Description:** (Empty text area)
- Parameter type:** Quantitative Parameter(Number,volume,etc)
- Parameter unit:** Meter
- Data Type:** Numeric
- Tolerance Accepted:** ☒
- Active:** ☒

## Critical Fields

1. Name : This field is used to mention the quality parameter name.

## Critical & onetime setup fields

1. Parameter Type : Used to mention the parameter type. (Ex : ( a)Qualitative Parameter(Good,Bad,etc) : This is based on the visual inspection, (b) Quantitative Parameter(Number,volume,etc) : This is based on the Particular parameters like , Length,Width,Weight)
2. Parameter Unit : Used to select the unit of the Parameter from the UOM master.
3. Data Type : Used to select the data type.(Boolean,Integer,Numeric,Text)

## Non-Critical Fields

1. Tolerance Accepted : If we select this check box it will accept the tolerance value .

**Zoom condition's**

**Customization**